

Sl No.	Name of work	Proposed	Status
1	Construction of 5.50LL OHSR at Mullassery	5.50LL OHSR, Compound wall, Valve chambers, Scour line, Flow meter	Completed except Scour line. Permission to be obtained from PMGSY to lay scour line. Flow meter not fixed
2	Construction of 6.70LL OHSR at Pavaratty	6.70LL OHSR, Compound wall, Valve chambers, Scour line, Flow meter	Completed. Flow meter not fixed