


INSPECTION REPORT			
IR NO.	MI/JJM-KWA/PALAKKAD/2020-21/656	DATE	25.02.2023
CLIENT	M/s. KERALA WATER AUTHORITY	CONTRACTOR	Sri PC SHAJI
CONTRACTOR'S PO/Agreement No.	17/2021-22/SE/PHC/PKD Dated.07.12.2021	DISTRICT	PALAKKAD
		HABITATION/ PANCHAYATH	MATHUR, PIRIYARI
		DIVISION.	PROJECT DIVISION PALAKKAD
MOODY AGREEMENT NO.	Work Order No. KWA/PD/CTR/DB-858/2021JJM/TPI	DATE	03.02.2021
NAME OF THE WORK	JJM – 2020-21 WSS to Mathur and Piriary Panchayats-12 MLD WTP ,14LL OHSR(Mathur),22LL OHSR(Piriary),Intake well ,RWPM,CWPM,Distribution system and FHTC's ,RW&CW Pumpsets and 400KVA Transformer.		
VALUE OF THE WORK	Agreement Amount: Rs. 61,18,75,389/- Value of work inspected: Rs.5,66,12,604/-)		
SCOPE OF WORK	1. Sample check of Documents (TC's) 2. Quality & Quantity check as per bills submitted 3. Functioning of works (FHTCs/Infrastructure Facilities)	Dates of Inspection	20.02.2023
INSPECTION CARRIED OUT	<input type="checkbox"/> Complete PO WORK	<input checked="" type="checkbox"/> Partial PO WORK	<input type="checkbox"/> Balance PO WORK
INSPECTION ACTIVITIES: Site inspection carried out (FHTCs on sampling basis) and the details of inspection are as follows : <ul style="list-style-type: none"> • CC 2nd Part of Bill contractor verified and found tallying as per work order/agreement given by KWA. • WTP, OHSR and Intake well inspection carried out. • WTP –Clarifier side wall completed,EW of filter house completed,Foundation upto plinth level of chemical house completed. • Intake well Side wall steining upto 9m. • 14LL OHSR(Mathur) upto 2nd brace completed • Laying of 14.52km done (PVC 90mm, 110mm, 140mm) and Supply of 90mm 6kg/cm², 110mm, 140mm and 160mm PVC pipes. • Visual inspection carried out for completeness and found to be satisfactory. • Workmanship and finish found to be satisfactory. 			
Note: This Inspection Report does not relieve the Contractor from any responsibility, or any contractual obligations or guarantees, not shall it be interpreted in any way so as to imply acceptance of the goods/works. Inspection is performed to the best of our ability, knowledge and belief but our organisation shall not be held responsible in any way whatsoever for the content of or technical accuracy of the purchase order/Agreement.			
DATE : 25.02.2023 PLACE: Hyderabad		 For MOODY INTERNATIONAL INDIA PVT.LTD	

INSPECTION PHOTOGRAPHS

Inspections WTP,OHSR and Intake well,Laying and Supply



Unnamed Road, Pirayiri, Kerala 678006, India
 Latitude 10.7672016666666665° Longitude 76.58922166666666°
 Local 09:22:36 AM Altitude 67 meters
 GMT 03:52:36 AM Monday, 20.02.2023



Mathur, Kerala, QH26+289, Mathur West, Kerala 678571, India
 Latitude 10.7503616666666667° Longitude 76.56041°
 Local 08:42:24 AM Altitude 86.1 meters
 GMT 03:12:24 AM Monday, 20.02.2023



Chakkanthara, Palakkad, Kerala 678006, India
 Latitude 10.7660150000000001° Longitude 76.584045°
 Local 09:04:04 AM Altitude 71.2 meters
 GMT 03:34:04 AM Monday, 20.02.2023



Mathur East, Kerala, India
 Latitude 10.7654666666666669° Longitude 76.583585°
 Local 09:02:15 AM Altitude 80.8 meters
 GMT 03:32:15 AM Monday, 20.02.2023

