


INSPECTION REPORT			
IR NO.	MI/JJM-KWA/PALAKKAD/2020-21/721	DATE	12.06.2023
CLIENT	M/s. KERALA WATER AUTHORITY	CONTRACTOR	Sri PC SHAJI
CONTRACTOR'S PO/Agreement No.	17/2021-22/SE/PHC/PKD Dated.07.12.2021	DISTRICT	PALAKKAD
		HABITATION/PANCHAYATH	MATHUR, PIRIYARI
		DIVISION.	PROJECT DIVISION PALAKKAD
MOODY AGREEMENT NO.	Work Order No. KWA/PD/CTR/DB-858/2021JJM/TPI	DATE	03.02.2021
NAME OF THE WORK	JJM – 2020-21 WSS to Mathur and Piriaryari Panchayats-12 MLD WTP ,14LL OHSR(Mathur),22LL OHSR(Piriaryari),Intake well ,RWPM,CWPM,Distribution system and FHTC's ,RW&CW Pumpsets and 400KVA Transformer.		
VALUE OF THE WORK	Agreement Amount: Rs. 61,18,75,389/- Value of work inspected: Rs.4,92,71,396/-) 4 th Part bill		
SCOPE OF WORK	1. Sample check of Documents (TC's) 2. Quality & Quantity check as per bills submitted 3. Functioning of works (FHTCs/Infrastructure Facilities)	Dates of Inspection	30.05.2023
INSPECTION CARRIED OUT	<input type="checkbox"/> Complete PO WORK	<input checked="" type="checkbox"/> Partial PO WORK	<input type="checkbox"/> Balance PO WORK
<p>INSPECTION ACTIVITIES: Site inspection carried out (FHTCs on sampling basis) and the details of inspection are as follows :</p> <ul style="list-style-type: none"> • CC 4th Part of Bill contractor verified and found tallying as per work order/agreement given by KWA. • 265nos HTCs,WTP, OHSR and Intake well, Laying and Supply inspection carried out. • WTP –Recycling arrangement upto RCC of base slab completed,Flash mixer side wall ,RCC for filter side wall gullet wall upto 2m completed. • Intake well cum pump house-side wall steining upto 15m, floor beam and floor slab of pump house,brick work completed. • Laying of 20.58km done(PVC 160mm,140mm,110mm,90mm Pipes) and Supply(90mm PVC 6kg/cm2 and 8kg/cm2 Pipes,300 mm DI,350mm DI,200mm DI,250mm DI) • 14LL OHSR(Mathur) upto 4th brace completed • Visual inspection carried out for completeness and found to be satisfactory. • Workmanship and finish found to be satisfactory. 			
<p>Note: This Inspection Report does not relieve the Contractor from any responsibility, or any contractual obligations or guarantees, not shall it be interpreted in any way so as to imply acceptance of the goods/works. Inspection is performed to the best of our ability, knowledge and belief but our organisation shall not be held responsible in any way whatsoever for the content of or technical accuracy of the purchase order/Agreement.</p>			
DATE : 12.06.2023 PLACE: Hyderabad		 For MOODY INTERNATIONAL INDIA PVT.LTD	

INSPECTION PHOTOGRAPHS

Inspections HTC's, WTP, OHSR and Intake well, Laying and Supply



QHCV+P4J, Melamuri Kottayi Rd, Pirayiri, Kerala 678006, India

Latitude 10.771654999999999°	Longitude 76.59275666666667°
Local 09:57:51 AM	Altitude 73 m
GMT 04:27:51 AM	Tuesday, 30.05.2023



Thachangad - Kuthiramada Temple Rd, Mathur East, Kerala 678571, India

Latitude 10.765025°	Longitude 76.58360833333333°
Local 09:40:12 AM	Altitude 70 m
GMT 04:10:12 AM	Tuesday, 30.05.2023



Mathur, Kerala, QH26+289, Mathur West, Kerala 678571, India

Latitude 10.750328333333334°	Longitude 76.5604°
Local 10:11:50 AM	Altitude 90 m
GMT 04:41:50 AM	Tuesday, 30.05.2023



Chakkanthara, Palakkad, Kerala 678006, India

Latitude 10.766083333333333°	Longitude 76.58399166666666°
Local 09:43:03 AM	Altitude 69 m
GMT 04:13:03 AM	Tuesday, 30.05.2023





Moody International India Pvt. Ltd, No. 719 B, 7th Floor , Manjeera Majestic Commercial, JNTUH-Hitech City Road, Beside Raythu Bazar, Hyderabad, Telangana- 500072, Board No. : 91 40 40262264, 65, Fax: +91 04 40262266