


INSPECTION REPORT			
IR NO.	MI/JJM-KWA/SHORANUR/2020-21/679	DATE	22.03.2023
CLIENT	M/s. KERALA WATER AUTHORITY	CONTRACTOR	Sri. Rameshan k
CONTRACTOR'S PO/Agreement No.	SE/PHC/PKD 18/22-23/SE/PHC/PKD, Dated: 01.10.2022	DISTRICT	PALAKKAD
		HABITATION/ PANCHAYATH	THACHAMPARA
		DIVISION.	PROJECT DIVISION PALAKKAD
MOODY AGREEMENT NO.	Work Order No.KWA/PD/CTR/DB-858/2021JJM/TPI	DATE	03.02.2021
NAME OF THE WORK	Jal Jeevan Mission-2020-2021 WSS to Thachampara Panchayat h- Supplying,Laying,Testing,Commissioning and Maintainence of distribution system with providing FHTCs 2735nos.		
VALUE OF THE WORK	Agreement Amount: Rs. 13,08,36,978/- (Value of work inspected: RS.1,16,15,765 /- 2 nd part bill)		
SCOPE OF WORK	1. Sample check of Documents (TC's) 2. Quality & Quantity check as per bills submitted 3. Functioning of works (FHTCs/Infrastructure Facilities)	Dates of Inspection	20.03.2023
INSPECTION CARRIED OUT	<input type="checkbox"/> Complete PO WORK	<input checked="" type="checkbox"/> Partial PO WORK	<input type="checkbox"/> Balance PO WORK
<p>INSPECTION ACTIVITIES: Site inspection carried out (FHTCs on sampling basis) and the details of inspection are as follows :</p> <ul style="list-style-type: none"> • 2nd part Bill contractor verified and found tallying as per work order/agreement given by KWA. • Laying of distribution line -14.944km (75mm,90mm,110mm HDPE pipes)and supply of PE100 PN10 90mm,PN12.5 90mm,PN8 110mm,PN12.5 110mm,PN10 110mm,140mm,PN12.5 140mm,PN8 160mm,75mm,PN10 75mm pipes inspection carried out. • Visual inspection carried out for completeness and found to be satisfactory. • Workmanship and finish found to be satisfactory. 			
<p>Note: This Inspection Report does not relieve the Contractor from any responsibility, or any contractual obligations or guarantees, not shall it be interpreted in any way so as to imply acceptance of the goods/works. Inspection is performed to the best of our ability, knowledge and belief but our organisation shall not be held responsible in any way whatsoever for the content of or technical accuracy of the purchase order/Agreement.</p>			
DATE : 22.03.2023 PLACE: Hyderabad		 For MOODY INTERNATIONAL INDIA PVT.LTD	

INSPECTION PHOTOGRAPHS

Inspections Laying (Distribution)



WGX8+62, Tachampara, Kerala 678593, India
 Latitude 10.947280000000001° Longitude 76.515435°
 Local 01:32:16 PM Altitude 87.1 meters
 GMT 08:02:16 AM Monday, 20.03.2023



WGW7+9Q, Karimba North, Kerala 678595, India
 Latitude 10.9449083333333334° Longitude 76.51364°
 Local 01:34:20 PM Altitude 89.1 meters
 GMT 08:04:20 AM Monday, 20.03.2023



WGW7+9Q, Karimba North, Kerala 678595, India
 Latitude 10.9467233333333333° Longitude 76.5129483333333333°
 Local 01:30:14 PM Altitude 75.9 meters
 GMT 08:00:14 AM Monday, 20.03.2023



WGXC+573, Kozhikode - Palakkad Hwy, Ponnampkode, Kerala 678593, India
 Latitude 10.9479300000000001° Longitude 76.52072°
 Local 01:23:18 PM Altitude 82.5 meters
 GMT 07:53:18 AM Monday, 20.03.2023





**Moody International India Pvt. Ltd, No. 719 B, 7th Floor , Manjeera Majestic Commercial, JNTUH-Hitech City Road,
Beside Raythu Bazar, Hyderabad, Telangana- 500072, Board No. : 91 40 40262264, 65, Fax: +91 04 40262266**