


INSPECTION REPORT			
IR NO.	MI/JJM-KWA/PALAKKAD/2020-21/743	DATE	22.07.2023
CLIENT	M/s. KERALA WATER AUTHORITY	CONTRACTOR	Sri BINU MATHEW
CONTRACTOR'S PO/Agreement No.	03/2022-23/SE/PHC/PKD Dated.30.05.2022	DISTRICT	PALAKKAD
		HABITATION/ PANCHAYATH	THENKARA
		DIVISION.	PROJECT DIVISION PALAKKAD
MOODY AGREEMENT NO.	Work Order No. KWA/PD/CTR/DB-858/2021JJM/TPI	DATE	03.02.2021
NAME OF THE WORK	JJM – CWSS to Thenkara ,Kanjirappuzha,Karakurissi and Thachampara Panchayats – Intake arrangement,RW Pumphouse,RW and CW pumpsets ,CWPM to Anamooli OHSR Construction of 14MLD WTP ,15LL OHSR at Anamooli for Thenkara Panchayat ,Supply and Erection of Transformers.		
VALUE OF THE WORK	Agreement Amount: Rs. 20,58,34,491/- Value of work inspected: Rs.2,92,25,627/-) 4 th Part bill		
SCOPE OF WORK	1. Sample check of Documents (TC's) 2. Quality & Quantity check as per bills submitted 3. Functioning of works (FHTCs/Infrastructure Facilities)	Dates of Inspection	21.07.2023
INSPECTION CARRIED OUT	<input type="checkbox"/> Complete PO WORK	<input checked="" type="checkbox"/> Partial PO WORK	<input type="checkbox"/> Balance PO WORK
<p>INSPECTION ACTIVITIES: Site inspection carried out (FHTCs on sampling basis) and the details of inspection are as follows :</p> <ul style="list-style-type: none"> CC 4th Part of Bill contractor verified and found tallying as per work order/agreement given by KWA. WTP-RCC base slab for filter house ,filter house side wall 3rd lift ,first floor slab and walkway,roof slab of filter house and base slab of wash water tank,clear water pumphouse completed,CLARIFLOCCULATOR-RCC upto 2nd lift,Roof slab of wash water tank completed,clear water pumphouse brickwork and plastering completed,FLASH MIXER-Earth work completed,Sump coverslab completed,CW Pumpset-3nos supplied. Visual inspection carried out for completeness and found to be satisfactory. Workmanship and finish found to be satisfactory. 			
<p>Note: This Inspection Report does not relieve the Contractor from any responsibility, or any contractual obligations or guarantees, not shall it be interpreted in any way so as to imply acceptance of the goods/works. Inspection is performed to the best of our ability, knowledge and belief but our organisation shall not be held responsible in any way whatsoever for the content of or technical accuracy of the purchase order/Agreement.</p>			
DATE : 22.07.2023 PLACE: Hyderabad		 For MOODY INTERNATIONAL INDIA PVT.LTD	

INSPECTION PHOTOGRAPHS

Inspections WTP



XGMQ+G9M, Palakkad, Kerala 678591, India

Latitude 10.9838133333333334° Longitude 76.53827°
Local 11:25:09 AM Altitude 93 m
GMT 05:55:09 AM Friday, 21.07.2023



XGMQ+G9M, Palakkad, Kerala 678591, India

Latitude 10.9838266666666667° Longitude 76.538351666666666°
Local 11:22:15 AM Altitude 89 m
GMT 05:52:15 AM Friday, 21.07.2023



XGMQ+G9M, Palakkad, Kerala 678591, India

Latitude 10.9838266666666667° Longitude 76.538295°
Local 11:22:18 AM Altitude 89 m
GMT 05:52:18 AM Friday, 21.07.2023



XGMQ+G9M, Palakkad, Kerala 678591, India

Latitude 10.9837800000000001° Longitude 76.538193333333333°
Local 11:22:43 AM Altitude 93 m
GMT 05:52:43 AM Friday, 21.07.2023





Moody International India Pvt. Ltd, No. 719 B, 7th Floor , Manjeera Majestic Commercial, JNTUH-Hitech City Road, Beside Raythu Bazar, Hyderabad, Telangana- 500072, Board No. : 91 40 40262264, 65, Fax: +91 04 40262266